



DIVERSIFIED
TESTING LABORATORIES, INC.
WORLDWIDE SERVICE

“We Test Per Your Request”

336 WEST FRONT STREET
P.O. BOX 4004
BURLINGTON, NORTH CAROLINA 27215
PHONE (336) 227-7710 • FAX (336) 227-1175
www.diversifiedtestinglabs.com

May 10, 2019

SOYANG TECHNOLOGIES CO., LTD
West 19th Fl, Yongtong Information Plaza
No. 141 Huancheng Bei Road
Hangzhou City, Zhejiang PR., China PC 310004

Reference: Laboratory Test Report
Lab Identification No. 35932
Invoice No. 67113

Dear Sir or Madam:

One (1) fabric ample, identified as **ST-302 (TENT)**, was received and tested in accordance with the California Administrative Code Title 19--Public Safety, Section 1237. Flame Resistance, Small Scale Test. The results are as follows:

<u>Specimen Number</u>	<u>Test Results</u>		<u>Char Length (in)</u>	
	<u>After Flame (sec)</u>			
	<u>Length</u>	<u>Width</u>	<u>Length</u>	<u>Width</u>
1	0.0	3.0	3.9	3.8
2	5.0	0.0	4.6	3.5
3	3.0	10.0	3.2	3.3
4	0.0	0.0	4.4	3.6
5	<u>0.0</u>	<u>0.0</u>	3.9	2.9
Avg.	1.6	2.6		

The sample submitted, in its original state, **meets** the minimum requirements of the above standard. The char length may not exceed 6.0 inches for any individual specimen and the average afterflame time may not exceed 4.0 seconds in the length or width directions.

If there are any questions or when we can be of further assistance, please let us know.

Sincerely,

Brian S. Dement

BSD/mr

